
## **WaveStar™ Software for Oscilloscopes**

WSTRO



# Software to Capture, Analyze, Document and Control Data

WaveStar<sup>™</sup> for Oscilloscopes is a Microsoft Windows application bringing measurement information to your Windows desktop.

#### **Capture**

Set up communication to instruments through the WaveStar Instrument Manager. The Explorer View displays these instruments and reveals their corresponding properties. To capture measurements, select a property, click, drag and drop into an active application sheet and begin analysis.

#### Analyze

Use up to twelve data sheets for analysis:

**Graticule Sheets** – Capture waveforms in YT or XY mode. Graphically view or edit multiple waveforms and masks on a graticule, with the same scale and position as the oscilloscope. Includes cursor measurements, horizontal and vertical gates, zoom function and annotation.

**Instrument Explorer Sheet** – Move and manipulate files to and from the MS Windows desktop or other instruments, add/delete directories, format drives and more.

**Stripchart Sheet** – Automatically plots multiple waveform measurements, such as rise time data, in a classic stripchart fashion. Sheet features cursor measurements, alarm control and annotation capabilities.

**Tabular Sheets –** Capture, store, display and edit either waveform or data log information as a table of numbers on corresponding sheets. The Scalar Viewer Sheet displays measurements from the oscilloscope.

**Measurement Sheet** – Calculate frequency, pulse width, rise/fall time, duty cycle, overshoot, peak-to-peak, amplitude, min, max, mean, cycle mean and RMS measurements.

**Harmonic Analysis Sheet** – Produce power waveforms from current and voltage and calculate up to 51 harmonics.

#### Features & Benefits

Capture Measurement Waveforms and Data Easily Without Programming

Create, Edit and Transfer Telecommunication Masks

Access, Organize, Move and Manipulate Instrument Files

Data Log Measurements from Single or Multiple Instruments

Perform Harmonic Analysis on Power Waveforms

Control Instrument Settings and Measurements Remotely from the PC

Works on Tektronix Open Windows Oscilloscopes

WaveStar Reader Application Included for Information Sharing

30-day WaveStar Product Evaluation Available at www.tektronix.com

## Applications

**Telecommunications** 

Digital Design

Research and Development

Manufacturing Test

Service

Education



## WaveStar™ Software for Oscilloscopes

▶ WSTRO

## Table 1. Tektronix Supported Instruments

Series*1	Restore*2	Settings*2	Picture*2
TDS200/1000/2000/3000B/ CSA8000B	Yes	Yes	Yes
TDS400/500/600/700/5000/			
6000/7000B/8000B/ CSA7000B	Yes	Yes	Yes
THS700	Yes	Yes	Yes

<sup>\*1</sup> Includes the newest DPO oscilloscopes.

**Notes Sheet** – Prepare simple reports; capture and save instrument hard copy; save, edit and restore instrument setups.

#### **Document**

Quickly and simply insert information into Microsoft Office applications, such as Excel, Word or PowerPoint. Transfer Information into Microsoft Windows applications, such as MATLAB, through the MS Windows clipboard.

#### Characteristics

#### **Software Compatibility**

**Instrument Interface Support –** GPIB, LAN, or RS-232 interfaces with full talk-listen modes.

**Windows Clipboard** – Drag and drop to compatible Microsoft Office applications or copy/paste through Windows clipboard.

**Printer Plotter Support** – Uses standard Microsoft Windows printer drivers.

**Waveform Export Format –** Microsoft Excel 6.0 compatible.

## Computer Configuration

#### Required -

Type: IBM PC-compatible.

Operating System: Windows 98SE/ME/2000/XP Pro or Windows NT 4.0, SP6+.

CD-ROM Drive: 4X or better.

Monitor: Super VGA.

### Recommended -

Processor: Pentium, 500 MHz.

RAM: 128 MB.

Instrument Interface Card: GPIB: National Instruments or CEC IEEE-488 Interface Card.

RS-232: One free RS-232 port.

Ethernet Interface Card: Inquire about Tektronix AD007, GPIB-LAN Adapter, TekVISA on Tektronix Open Windows Oscilloscopes.

## Ordering Information

#### **WSTRO**

WaveStar Software for Oscilloscopes, Microsoft Windows 98/ME/2000/NT 4.0 version. **Includes:** CD-ROM, manual (071-0220-XX).

**Brazil & South America** 55 (11) 3741-8360

ASEAN / Australasia / Pakistan (65) 6356 3900

Canada 1 (800) 661-5625

Contact Tektronix:

**Austria** +43 2236 8092 262 **Belgium** +32 (2) 715 89 70

Central Europe & Greece +43 2236 8092 301

Denmark +45 44 850 700

Finland +358 (9) 4783 400

France & North Africa +33 (0) 1 69 86 80 34

Germany +49 (221) 94 77 400

Hong Kong (852) 2585-6688

India (91) 80-2275577

Italy +39 (02) 25086 1

Japan 81 (3) 3448-3010

Mexico, Central America & Caribbean 52 (55) 56666-333

The Netherlands +31 (0) 23 569 5555

Norway +47 22 07 07 00

**People's Republic of China** 86 (10) 6235 1230

Poland +48 (0) 22 521 53 40

Republic of Korea 82 (2) 528-5299

Russia, CIS & The Baltics +358 (9) 4783 400

South Africa +27 11 254 8360

Spain +34 (91) 372 6055

Sweden +46 8 477 6503/4

Taiwan 886 (2) 2722-9622

United Kingdom & Eire +44 (0) 1344 392400

**USA** 1 (800) 426-2200

USA (Export Sales) 1 (503) 627-1916

For other areas contact Tektronix, Inc. at: 1 (503) 627-7111

Updated 20 September 2002

Our most up-to-date product information is available at: www.tektronix.com



Copyright © 2003, Tektronix, Inc. All rights reserved. Tektronix products are covered by U.S. and foreign patents, issued and pending, Information in this publication supersedes that in all previously published material. Specification and price change privileges reserved. TEKTRONIX and TEK are registered trademarks of Tektronix, Inc. All other trade names referenced are the service marks, trademarks or registered trademarks of their respective companies.

10/03 HB/WWW 60W-12123-5

Tektronix

Enabling Innovation

2 Software • www.tektronix.com/accessories

<sup>\*2</sup> Restore waveforms, acquire/restore settings, acquire picture.